

avFAB

CRS Services Catalog



45
YEARS OF
AVIATION
EXCELLENCE



Please contact us at Sales@AvFab.com for a free quote and current lead time estimate for your particular aircraft's service needs.



**FAA – Parts Manufacturing Approval Facility
#PQ3012CE**

**FAA – Certified Repair Station
#GVRR304K**



**EASA – U.S. Approval Certificate
#EASA 145.5546**



**CAA – Maintenance Organisation Approval
Certificate #UK.145.50319**


Table of Contents

Seat Recline Cylinder	4-5
Toilets	6-7
Interior Components	8-9
Window Shade Repair	10-11
Seat Repair	12-13
Heated Liquid Containers	14-15

Seat Recline Cylinder

Lead Time: AvFab will and/or overhaul your actuators within 2 working days after receipt of unit. Same day service is normally available if you need faster turn time.

Warranty: Each unit includes a one-year warranty from date of overhaul, provided it has not been abused, altered or subject to abnormal use.




avFAB
AVIATION FABRICATORS

The World Leader

in General Aviation Seat Recline Cylinder Overhauls

AvFab pioneered the quick-turn overhaul of seat recline cylinders, performing hundreds of these FAA-approved repairs every month. Your P.L. Porter, Enidine, Roton and Sicma cylinders can be made like new at a fraction of the cost of replacement. Plus, your AvFab-repaired cylinder comes with FAA 8130-3 or EASA Form 1 Dual Release Return to Service documentation and it has the same warranty as a new cylinder. Turn times are two to four days. If exchange units are available, you may even be able to have parts the next day.

Recline and relax. We've got your back.



Call us today at:
(660) 885-8317 / www.AvFab.com

Seat Recline Cylinder

Capabilities List


Seat Cylinders	Beechcraft	36-380064- Series, 106-384001-Series
	Enidine	UL18- Series, UL32- Series, UL37-010, 060 Series, SP22322, SP22323, SP22090 & SP23422
	PL Porter	HL10000, HL17500, HL25200, HL01400, HL08700, HL08800 Series, HL08900 Series, LL75000, LL25000, LL26000, LL01500, LL11200, LL15000, LL17500, LL06500, and LL02000, LL22500-10, SL02300, SL03300, SL02900, SL02500, SL04300, SL10XXX, SL06300, SL4500 and SL6000 Series, HV08000, HV10000 and HL11200 Series, HM07500-00, HM17500-80, HM17500-85, HM17500-18, HM25200-00, HM10000-138, HV25000-04 and LL1400-06
	Roton	19XXX Series
	Sicma	Models 8126



Toilets

Lead Time: Normally 5 to 10 working days to complete the repair/modification on customer toilet.

Warranty: Each unit includes a one-year warranty from date of overhaul, provided it has not been abused, altered or subject to abnormal use.



Toilet Repair Capabilities List

Aircraft Technologies	10, 31A, 40, 42, 50 and 90 Series
Alamo/Clean Flush	9600-1, 9700-1
Envirovac	Ipeco
Monogram	Models 4620, 12300, 13450, 14350, 15300, 15500, 15730, 15900, 17000, 17010, 17020, 7900268, 7900269, 7900368 and 7900369 Series
Weber, Koehler	Models 25, 45, 105, 125, 145 & 835881, 144805 Series
Monogram	7800000 series and 7800028-006

BEFORE



AFTER





Sample Tank Repair

Interior Cabin Components

Lead Time: Variable, contact us for an accurate time estimate.

Warranty: Each unit includes a one-year warranty from date of overhaul, provided it has not been abused, altered or subject to abnormal use.



Out With the Old...



...in with the New!

Update your Citation with an AvFab Aft Pocket Divider
AvFab's Cessna Citation Aft Pocket Dividers replace the original hard to operate factory aft partitions and accordion door with an easy to operate system, giving the aircraft a modern look.

Interior Capabilities List

Bombardier Challenger	Models CL-600, CL-601, CL-604 series and Global Express
British Aerospace	Models 3101, and 3201 Series Models 150, 152, 170, 172, 175, 177, 180, 182, 185, 188, 205, 206, 207, 208, 210, 303, 310, 320, 335, 336, 337, 340, 401, 402, 404, 411, 414, 421, 425 and 441 series
Cessna	
Cessna Citation	Models 500, 501, 525, 550, S550, 551, 560 and 650 Series
Dassault Falcon	Models 10, 100, 20, 200, 50, and 900 Series
Enflite	Models 22080, 22250, 22271, 22280, 52900, 53300, 22092, 52960, 54900, 54950, 54950Z, 54975, 55000, 55100, 55150, 22164, 22164Z, 22165, 22188, 22188Z, 22188Z1, 22290, 52400, 52500, 52800, 53900, 54400, 54450, 54460, 54500, 54550, 54600, 54650, 54700, 55500, 52875, 55850, 52810, 52820, 52830, 52860, 22210, 53100, 53150, 53175, 54200, 54250, 54275, 22345, 53700, 53750, 53775, 53800 Series
Fairchild	Models SA26, SA26T, SA26AT, SA226, SA226T, SA226AT, SA226TC, SA227, SA227AC, SA227AT, SA227TT Series
Gulfstream	Models G-159, G-1159, G-IV, and G-V Series
Hawker Beechcraft	Models DH-125, BH-125, BAE-125, 400, 600, 700, 800 and 1000 Series
Hawker Beechcraft	Models 33, 35, 36, 55, 56, 58, 60, 65, 80, 88 Series
Hawker Beechcraft KA	Models , 90, 99, 100, 200, 300 Series
Israel Aircraft Industries	Models 1121, 1122, 1123, 1124, and 1125 Series
Learjet	Models 23, 24, 25, 28, 29, 31, 35, 36, 45, 55, and 60 Series
Piper	Models PA-18, PA-20, PA-22, PA-23, PA-24, PA-25, PA-28, PA-30, PA-31, PA-32, PA-34, PA-36, PA-42, PA-44, and PA-46 Series
Raytheon/Beechcraft	1900 Series
Sabreliner	Models NA-265-20, -30, -40, -60, -65, -70 and -80 Series
Twin Commander	Models 500, 520, 560, 680, 681, 685, 690, and 695 Series

Window Shade Refurbishment

Lead Time: Typically two weeks.

Warranty: Each unit includes a one-year warranty from date of refurbishment, provided it has not been abused, altered or subject to abnormal use.



Window Shade Color Samples



Gray



Dove



Slate



Olivine



Tan



Limestone



Request a Quote



Window Shade Repair List

A & C Products	CHDX11-, CH650-01- Series
Aerospace Technologies Group	ATG-WS Series, WSFA-20 Series, ATG20F0-Series, ATG21F0-Series
Aviation Fabricators	32-0387, 32-0438, 32-0517, 32-0556
Beechcraft	Beechjet 400 series, Premier 390
Bomhoff	7603027 Series
Citation	All models including Mustang
Embraer	Phenom 100 & 300, Praetor 500 & 600
Fischer Advanced Composite Components	M6613127-, 253-49090-005- Series
Global Engineering	390-384029 Series, 390-384030 Series
Learjet	6320-3000-Series
Lou Martin & Assoc	S60-113M008 Series, L35-113 Series, CL601-113M Series, 125-113M Series, CIT3-113M Series, F10-113M Series, F50-113M Series, GALX-113M Series, Piaggio 180 Series, Global 5000 Series, F50-113M014-1
MSA Aircraft Prod	Models 003- 005- 006- 007- 008- Series
Pilatus	Model 525.24.12.101 Series, 525.24.12.100 Series, 525.24.12.099 Series
Piper	PA-46
Precision	12410-, 401-384048-, 132-384007-, 7603027-Series

Seat Repair Services

Lead Time: Variable, contact us for an accurate time estimate.

Warranty: Each unit includes a one-year warranty from date of overhaul, provided it has not been abused, altered or subject to abnormal use.



Seat Repair List

4 Flight Industries	105, 10320, 11875, 12715, 12805, 3080, 3580, 3585, 4040, 6620, 7115, 8565 and 8990 Series 4128- Series Models 900
Aircraft Modular Products	Series, Basic P/N 2524 & 2523, Gulfstream V P/N 2524.525, Generic P/N 2524.528, 2524.518, 2524.014.01, 2524.516.01-(), 2524.513.01, 2524.517.01-(), 2524.027, 2524.523 Series
BE Aerospace	Models 8788 and 900 Series, 2524.026, 2524.207, 2524.526, 2524.507, 2524.517-01
Beechcraft	Model 300
Cessna Citation	Models 500, 501, 525, 550, S550, 551, 560 and 650 Series
Custom Products	All Models
Decrane/ERDA	Models 1033000, 1083200-1 through -18, 3130, 3040, 3043, 3067, 3089, 3307, 3415, 3437, 3438, 3442, 3444, 4006, 4007, 4018, 4034, A13439, A12604, A14204, A15236, A16402GL, 11032-B, 14104SB, 80A16S3, 80A42S2, 17000, 5000 Series
Derlan	1083000-1, 1083000-2, 1083000-3, 1083000-4, 1083000-5, 1083000-6, 1083000-7, 1083000-8, 1083000-9, 1083000-10, 1083200-Series
ERDA, Inc	Models 3000, 3156 & 3439 Series, All Divan Models
Goodrich	3069, 4049, 303585 Series
IAI Golan Industries	5PC22000- series
Ipeco, Inc	Models 3A053, 3A032, 3A035, 3A026, 3A029, 3A400 and 3A403, 3A213 Series
Millenninm	Model 2033 Series
Precision Aircraft Components	Divan Model GS400A
PTC Aerospace	Models 912 series, 936 Series
Sicma	Models 394, 397, 398, 262, 263, 317, A317, 377, and A377 Series
Sogerma-Socea	TABH1-00PM00-01 & TABH1-00CM00-01, TALJ2-Series
Tossington Enterprise	Models T1280 Series
Weber	Models 5300 Series
Zodiac	Divan Models, 41321001-, 41322001-, 41323001-, 41324001-Series

Coffee Brewers & Heated Liquid Containers

Lead Time: AvFab will repair or overhaul your liquid heated container within 5 working days after receipt of unit.

Warranty: Each unit includes a one-year warranty from date of overhaul, provided it has not been abused, altered or subject to abnormal use.



HLC Repair List

TIA	Model 1459
Adams Rite Aerospace	Models AR9061, AR9062, AR9063 Series
Aircraft Products	1359 and 764 Series
BE Aerospace	Models 180 series, 297 Series, 306 Series, 800-8938-1
Bomhoff	Model M3113093 Series
Creative Interiors	Models 6600486- Series
Custom A/C Conversions	Models BDD5.0020-2
Electrotherm	Models EL-M-100/28C, EL-M-100/28EX and EL-M-150/28C
FL Aerospace	306 and 610 Series
Global Engineering	Model 130, 190 & 200 series
Grimes Mapco	Models 1158, 1290 and 1388 Series
Hawker Beechcraft	Models 138-530942- Series, 800-8938-1
Hiller	Model HLWC03205, H45SSWC-02001-1, H45PWC-02001-1, HLWC-03504 Series, H45WC-02007 Series, H45WC-04001 Series & H60WC02001- Series
Maynard, Inc	Models A1-AW-007-15, 99R489 and 138-530489 Series
Midland Ross	1060, 1095 and 1097 Series
Midwest Aircraft Products	Models 1187, 1189, 1247, 1248, 1251, 1268 and 1290 Series
Precision Pattern/Goodrich	Models 13222, 80037, 81366, 81319, 81314, 81315, 017-, 80605, 8390, 81246, 81303, 81318, 81355, 81377, 81391, 81441, 12614, 12779, 81328, 80829, 80181, 81434, BDD5.0020- Series, 6607024- and F50 Series, S2800 Series, S4482 Series, 8571-13 Series, 80258 Series, 81463 Series
Textron	Model 81475- Series

Coffee Brewers

TIA Electric	Models 400, 1448, 1601, 1602, 1603 Series MB201,
Aerospace Aerolux/AMC	MB2004, ALCB28 & AL-EX15-200E Series Models
Nordskog/BE Aerospace	50413, 3510- and 50405- Series



AVIATION FABRICATORS
805 N FOURTH ST.
CLINTON, MO 64735 (660)
885 - 8317
SALES@AVFAB.COM