AvFab CRS Services











Please contact us at Sales@AvFab.com for a free quote and current lead time estimate for your particular aircraft service needs.

FAA - Parts Maunfacturing Approval Facility - #PQ3012CE FAA - Certified Repair Station - #GVRR304K





Table of Contents

Seat Recline Cylinder	4-5
Toilets	6-7
Interior Components	8-9
Window Shade Repair	10-11
Seat Repair	12-13
Heated Liquid Containers	14-15



Seat Recline Cylinder

Lead Time: AvFab will and/or overhaul your actuators within 2 working days after receipt of unit. Same day service is normally available if you need faster turn time.





Beechcraft	36-380064- Series, 106-384001-Series
Enidine	UL32- Series, UL37-010, 060 Series, SP22322, SP22323 & SP22090
Liliulile	HL10000, HL17500, HL25200, HL01400, HL08700, HL08800
	Series, HL08900 Series, LL75000, LL25000, LL26000,
	LL01500, LL11200, LL15000, LL17500, LL06500, and LL02000,
	LL22500-10, SL02300, SL03300, SL02900, SL02500, SL04300,
	SL10XXX, SL06300, SL4500 and SL6000 Series, HV08000,
	HV10000 and HL11200 Series, HM17500-80, HM17500-85,
PL Porter	HM17500-18, HM25200-00
Roton	19XXX Series
Sicma	Models 8126

Toilets

Lead Time: Normally 5 to 10 working days to complete the repair/modification on customer toilet.





Aircraft Technologies	10, 31A, 40, 42, 50 and 90 Series
Alamo/Clean Flush	9600-1, 9700-1
Envirovac	7900151, 7900152
	Models 4620, 12300, 13450, 14350, 15300, 15500, 15730,
	15900, 17000, 17010, 17020, 7900268, 7900269, 7900368
Monogram	and 7900369 Series
Weber, Koehler	Models 25, 45, 105, 125, 145 & 835881, 144805 Series
Monogram	7800000 series and 7800028-006

Interior Components

Lead Time: Variable, contact us for an accurate time estimate.









	•
Bombardier Challenger	Models CL-600, CL-601, CL-604 series and Global Express
British Aerospace	Models 3101, and 3201 Series
	Models 150, 152, 170, 172, 175, 177, 180, 182, 185, 188,
	205, 206, 207, 208, 210, 303, 310, 320, 335, 336, 337, 340,
Cessna	401, 402, 404, 411, 414, 421, 425 and 441 series
Cessna Citation	Models 500, 501, 525, 550, S550, 551, 560 and 650 Series
Dassault Falcon	Models 10, 100, 20, 200, 50, and 900 Series
	Models 22080, 22250, 22271, 22280, 52900, 53300, 22092,
	52960, 54900, 54950, 54950Z, 54975, 55000, 55100, 55150,
	22164, 22164Z, 22165, 22188, 22188Z, 22188Z1, 22290,
	52400, 52500, 52800, 53900, 54400, 54450, 54460, 54500,
	54550, 54600, 54650, 54700, 55500, 52875, 55850, 52810,
	52820, 52830, 52860, 22210, 53100, 53150, 53175, 54200,
Enflite	54250, 54275 Series
	Models SA26, SA26T, SA26AT, SA226, SA226T, SA226AT,
Fairchild	SA226TC, SA227, SA227AC, SA227AT, SA227TT Series
Gulfstream	Models G-159, G-1159, G-IV, and G-V Series
	Models DH-125, BH-125, BAE-125, 400, 600, 700, 800 and
Hawker Beechcraft	1000 Series
Hawker Beechcraft	Models 33, 35, 36, 55, 56, 58, 60, 65, 80, 88 Series
Hawker Beechcraft KA	Models , 90, 99, 100, 200, 300 Series
Israel Aircraft Industries	Models 1121, 1122, 1123, 1124, and 1125 Series
Learjet	Models 23, 24, 25, 28, 29, 31, 35, 36, 45, 55, and 60 Series
	Models PA-18, PA-20, PA-22, PA-23, PA-24, PA-25, PA-28,
	PA-30, PA-31, PA-32, PA-34, PA-36, PA-42, PA-44, and PA-
Piper	46 Series
Raytheon/Beechcraft	1900 Series
Sabreliner	Models NA-265-20, -30, -40, -60, -65, -70 and -80 Series
Twin Commander	Models 500, 520, 560, 680, 681, 685, 690, and 695 Series
i win Commander	wodels 500, 520, 560, 680, 681, 685, 690, and 695 Series



Window Shade Repair

Lead Time: Variable, contact us for an accurate time estimate.

Warranty: Each unit includes a one year warranty from date of overhaul, provided it has not been abused, altered or subject to abnormal use.

AvFab offers repairs for these window shades as well as the option to purchase Window Shade Material directly from us.








Aerospace Technologies Group	ATG-WS Series, WSFA-20 Series
Aviation Fabricators	32-0387, 32-0438
Bomhoff	7603027 Series
Fischer Advanced Composite	
Components	M6613127- Series
Global Engineering	390-384029 Series, 390-384030 Series
Learjet	6320-3000-Series
	S60-113M008 Series, L35-113 Series, CL601-113M Series,
	125-113M Series, CIT3-113M Series, F10-113M Series,
	F50-113M Series, GALX-113M Series, Piaggio 180 Series,
Lou Martin & Assoc	Global 5000 Series
MSA Aircraft Prod	Models 003- 005- 006- 007- 008- Series
	Model 525.24.12.101 Series, 525.24.12.100 Series,
Pilatus	525.24.12.099 Series
Precision	12410-, 401-384048-, 132-384007-, 7603027- Series





Seat Repair Services

Lead Time: Variable, contact us for an accurate time estimate.











	105, 10320, 11875, 12715, 12805, 3080, 3580, 3585, 4040,
4 Flight Industries	6620, 7115, 8565 and 8990 Series 4128- Series
	Models 900 Series, Basic P/N 2524 & 2523, Gulfstream V
	P/N 2524.525, Generic P/N 2524.528, 2524.518,
	2524.014.01, 2524.516.01-(), 2524.513.01, 2524.517.01-(),
Aircraft Modular Products	2524.027
	Models 8788 and 900 Series, 2524.026, 2524.207, 2524.526,
BE Aerospace	2524.507, 2524.517-01
Beechcraft	Model 300
Cessna Citation	Models 500, 501, 525, 550, S550, 551, 560 and 650 Series
Custom Products	All Models
Decrane/ERDA	Models 1033000, 1083200-1 through -18, 3130, 3040, 3043,
	3067, 3089, 3307, 3415, 3437, 3438, 3442, 3444, 4006, 4007,
	4018, 4034, A13439, A12604, A14204, A15236,
	A16402GL, 11032-B, 14104SB, 80A16S3, 80A42S2, 17000,
	5000 Series
	1083000-1, 1083000-2, 1083000-3, 1083000-4, 1083000-5,
	1083000-6, 1083000-7, 1083000-8, 1083000-9, 1083000-10,
Derlan	1083200-Series
ERDA, Inc	Models 3000, 3156 & 3439 Series, All Divan Models
Goodrich	3069, 4049
IAI Golan Industries	5PC22000- series
	Models 3A053, 3A032, 3A035, 3A026, 3A029 and 3A400
Ipeco, Inc	Series
Millenninm	Model 2033 Series
Precision Aircraft Components	Divan Model GS400A
PTC Aerospace	Models 912 series, 936 Series
	Models 394, 397, 398, 262, 263, 317, A317, 377, and A377
Sicma	Series
Sogerma-Socea	TABH1-00PM00-01 & TABH1-00CM00-01
Tossington Enterprise	Models T1280 Series
Weber	Models 5300 Series
	Divan Models, 41321001-, 41322001-, 41323001-, 41324001-
Zodiac	Series



Coffee and Heated Liquid Containers

Lead Time: AvFab will repair or overhaul your liquid heated container within 5 working days after receipt of unit.







÷ 9-10	
	P/N 8921082-G1, -G2, -G5, -G6, 8921340G1, 8921460G3,
GE, BF Goodrich	G4, G5, G6, G7, 24E507040G01, G02, G03, G04, G05
TIA	Model 1459
Adams Rite Aerospace	Models AR9061, AR9062, AR9063 Series
Aircraft Products	1359 and 764 Series
BE Aerospace	Models 180 series, 297 Series, 306 Series, 800-8938-1
Bomhoff	Model M3113093 Series
Creative Interiors	Models 6600486- Series
Custom A/C Conversions	Models BDD5.0020-2
Electrotherm	Models EL-M-100/28C, EL-M-100/28EX and EL-M-150/28C
FL Aerospace	306 and 610 Series
Global Engineering	Model 130, 190 & 200 series
Grimes Mapco	Models 1158, 1290 and 1388 Series
Hawker Beechcraft	Models 138-530942- Series, 800-8938-1
	Model HLWC03205, H45SSWC-02001-1, H45PWC-02001-1,
	HLWC-03504 Series, H45WC-02007 Series, H45WC-04001
Hiller	Series & H60WC02001- Series
Maynard, Inc	Models A1-AW-007-15, 99R489 and 138-530489 Series
Midland Ross	1060, 1095 and 1097 Series
	Models 1187, 1189, 1247, 1248, 1251, 1268 and 1290
Midwest Aircraft Products	Series
	Models 13222, 80037, 81366, 81319, 81314, 81315, 017-,
	80605, 8390, 81246, 81303, 81318, 81355, 81377, 81391,
	81441,12614, 12779, 81328, 80829, 80181, 81434,
	BDD5.0020- Series, 6607024- and F50 Series, S2800
Precision Pattern/Goodrich	Series, S4482 Series, 8571-13 Series, 80258 Series
Textron	Model 81475- Series

Coffee Brewers

TIA Electric	Models 400, 1448, 1601, 1602, 1603 Series
Aerospace Aerolux/AMC	MB201, MB2004, ALCB28 & AL-EX15-200E Series
Nordskog/BE Aerospace	Models 50413, 3510- and 50405- Series





AVIATION FABRICATORS

805 N FOURTH ST.

CLINTON, MO 64735

(660) 885 - 8317

SALES@AVFAB.COM