

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA00057WI	10/22/03	Commuter Seats	72-0134	Piper	PA-31, PA-31-300, PA-31-325, PA-31-350
SA00068WI	05/25/93	Stretcher	32-0114, 32-0196	Hawker Beechcraft	36, A36, A36TC, B36TC, 58, 58A, 58TC, 58TCA
SA00103WI	01/20/11	Heated Windshield Panel	42-0118K, 42-0187K, 42-0272K, 42-0274K	Cessna	401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C, 425, 404, 406
SA00419WI	04/11/96	Underseat Drawers	42-0242K, 42-0243K, 42-0244K 42-0245K	Cessna	335, 340, 340A
SA00453WI	06/10/96	Lateral Tracking Seat Base	32-0240, 32-0241, 32-0357, 32-0358	Hawker Beechcraft	65-90, 65-A90, B90, C90, E90, H90, C90A, 100, A100, A100A, A100C, B100, 200, 200C, 200T, 200CT, A200, A200C, A200CT, B200, B200C, B200T, B200CT, 300, 300LW, B300, B300C, F90
SA00622WI	01/28/98	Shoulder Harness Anchor	32-0181K	Hawker Beechcraft	65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 65-88, 65-90, 65-A90, 65-A90-1, 65-A90-2, 65-A90-3, 65-A90-4, 70, B90, C90, C90A, C90GT, C90GTi, E90, H90, 99, 99A, A99, A99A, B99, C99, 100, A100, A100A, A100C, B100, 200, 200C, 200T, 200CT, A200, A200C, A200CT, B200, B200C, B200T, B200CT, B200GT, B200CGT, 300, 300LW, B300, B300C, F90
SA00635WI	07/30/13	Jump Seat	32-0210K-XX	Hawker Beechcraft	100, A100, A100A, A100C, B100, 200, 200C, 200T, 200CT, A200, A200C, A200CT, B200, B200C, B200T, B200CT, 300, 300LW, B300, B300C, C90, C90A, C90GT, C90GTi, E90, B200GT, B200CGT
SA00833WI	11/05/99	Seat Headrest	42-0247-100, 42-0247-200	Cessna	401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C, 425, 404, 406, 441, 500, 550, S550, 552, 560, 501, 551, 650
SA00873WI	11/05/08	Tailcone Assembly	42-0225	Cessna	310P, 310Q, 310R, T310P, T310Q, T310R
SA00961WI	02/01/10	Stretcher	72-0176, 72-0189, 72-0386, 72-0388	Piper	PA-31P, PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-31P-350, PA-31, PA-31-300, PA-31-325, PA-31-350, PA-42, PA-42-720, PA-42-1000
SA00963WI	04/24/01	Heated Windshield Panel	72-0275K, 72-0276K, 72-0277K, 72-0278K	Piper	PA-31, PA-31-300, PA-31-325, PA-31-350
SA01046WI	01/16/02	2-PL Side Facing Divan	52-0306K, 52-0307K	British Aerospace	3101, 3201
SA01574WI	03/11/10	Table Assemblies	32-0368K	Hawker Beechcraft	1900D

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA01576WI	03/08/10	Seat Headrest	32-0349K, 32-0407K	Hawker Beechcraft	C90, C90A, E90, F90, A100, B100, 200, 200T, 200C, 200CT, B200, 300
SA01638WI	07/28/11	Arm Ledge System & Table Assembly	32-0343, 32-0344K	Hawker Beechcraft	C90, C90A, E90, H90, F90, 200, 200T, 200C, 200CT, B200, B200C, B200T, B200CT
SA01672WI	2/10/2012, Amended 4/26/17	Window Shade Assembly	32-0438(000)K, 32-0438(292)K, 32-0438(741)K	Hawker Beechcraft	200, 200C, 200CT, 200T, B200, B200C, B200CT, B200T, B200GT, B200CGT, C90 series including C90GTi, E90 and F90
SA01809WI	10/11/16	KA Special Mission Aircraft Operator Seat	32-0397	Beechcraft	90, 99, 100, 200, 300, B300, (350)
SA01825WI	10/20/16	Stretcher	62-0428, 62-0449	Pilatus	PC-12, PC-12/45, PC12-47, PC12-47E
SA02468LA	01/07/16	AFT Toilet Cabinet Seat	32-0328K-1, 32-0385K	Hawker Beechcraft	200, 200C, 200CT, 200T, B200, B200C, B200CT, B200T, B200GT, B200CGT, B300, B300C
SA100RM	07/27/98	Forward Lounge Toilet	42-0211K, 42-0212K, 42-0213K, 42-0214K	Cessna	500, 550, 501
SA1130SW	12/12/03	Side Facing Divan	72-0154, 72-0173, 72-0342	Piper	PA-31P, PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-31P-350, PA-31, PA-31-300, PA-31-325, PA-31-350, PA-42, PA-42-720, PA-42-1000
SA1131SW	06/15/04	Side Facing Divan	42-0143, 42-0148, 42-0353	Cessna	401, 402, 411, 414, 421, 425 (All Series)
SA1132SW	08/10/02	Side Facing Divan	62-0170, 62-0171, 62-0279, 62-0280, 62-0281, 62-0282	Learjet	23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 31, 31A, 35, 35A(C-21A), 36, 36A
SA117RM	03/16/08	3-PL AFT Couch	90500-1, 90500-101, 90500-102, 90500-103, 90500-104, 90530-1, 90530-101, 90750-1, 90750-101, 90750-102, 90750-103, 90750-104, 90750-105	Cessna	501, 551
SA1187SW	06/20/03	Side Facing Couch	52-0162, 52-0163, 52-0164	Fairchild Aircraft	SA26-AT, SA26-T, SA226-T, SA226-T(B), SA227-TT

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA125RM	02/06/04	Tailcone Ski Rack	42-0174K, 42-01745K, 42-0249K, 42-0250K	Cessna	501, 551
SA126RM	06/30/03	Stretcher	42-0197K-1, 42-0197K-11, 42-0197K-21, 42-0197K-31, 42-0197K-41, 42-0197K-51 42-0197K-61, 42-0197K-71, 42-0197K-81, 42-0197K-91, 42-0198K-1, 42-0198K-2	Cessna	501, 551
SA1310SW	11/18/93	Stretcher	73-0101, 73-0103, 73-0105	Piper	PA-32-260, PA-32-300, PA-32R-300, PA-32-RT300, PA-32-RT300T, PA-32R-301T, PA-32-301, PA-32-R301, PA-32-301T, PA-34-200, PA-34-200T, PA-34-220T
SA148SW	11/09/82	Stretcher		Piper	PA-23, PA-23-250, PA-24, PA-28-150, PA-28-160, PA-28-180, PA-28-235, PA-30
SA1744SO	11/12/88	Two Nacelle Locker Metal		Piper	PA-31, PA-32-325, PA-31-350
SA177RM	04/19/01	Single Seat in AFT Baggage Compartment	90270-1	Cessna	501
SA1897WE	12/28/90	AFT Baggage Compartment	42-0119	Cessna	421, 421A, 421B
SA203SW	11/09/82	Stretcher	42-0109	Cessna	336

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA2-1178	11/14/01	Stretcher	41-0110	Cessna	170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F, 172G, 172H, 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172RG, 175, 175A, 175B, 175C, 177, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182, T182, TR182, 185, 185A, 185B, 185C, 185D, 185E, 185F, 206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, U206G, TP206A, TP206B, TP206C, TP206D, TP206E, TP206F, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G, 207, 207A, T207, T207A, 210-5(205), 210-5A(205A), 210, 210A, 210B, 210C, 210D, 210E, 210F, 210G, 210H, 210J, 210K, 210L, 210M, 210N, 210R, T210
SA2349SW	05/06/06	3-PL Side Facing Divan	32-0100, 32-0209, 32-0260, 32-0336, 32-0337, 32-0338, 32-0339	Hawker Beechcraft	65, A65, 65-80, 65-A80, 65-B80, 65-90, 65-A90, B90, C90, E90, F90, 100, A100, B100, 200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, 300, B300, B300C, 300LW
SA2364CE	03/18/88	Stretcher	42-0115	Cessna	337, 337A, 337B, M337B, T337B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, 337H, P337H, T337H
SA2582CE	02/08/90	Auxiliary Seat	41-0116	Cessna	150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, 152, A152
SA2583CE	02/08/90	Auxiliary Seat	41-0116	Reims	F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FRA150L, FRA150M, F152, FA152
SA2626CE	01/28/03	2-PL Side Facing Divan	32-0112, 32-0150, 32-0222, 32-0239, 32-0257, 32-0370, 32-0371	Hawker Beechcraft	65, A65, 65-80, 65-A80, 65-88, 65-90, 65-A80-8800, 65-A90, B90, C90, E90, 65-B80, A65-S200, C90A, H90, 70
SA2627CE	01/28/03	2-PL Side Facing Divan	32-0112, 32-0150, 32-0222, 32-0239, 32-0257, 32-0370, 32-0371	Hawker Beechcraft	F90
SA2628CE	01/28/03	2-PL Side Facing Divan	32-0112, 32-0150, 32-0222, 32-0239, 32-0257, 32-0370, 32-0371	Hawker Beechcraft	99, 99A, A99A, B99, C99, 100, A100, A100A, A100C, B100
SA2629CE	04/17/08	2-PL Side Facing Divan	32-0112, 32-0150, 32-0222, 32-0239, 32-0257, 32-0370, 32-0371	Hawker Beechcraft	200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, B200GT, <b>B200CGT</b> , 300, 300LW, B300, B300C

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA2630CE	07/23/08	4-PL Side Facing Divan	32-0149, 32-0133, 32-0194, 32-0248, 32-0227, 32-0355, 32-0362	Hawker Beechcraft	65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 65-88, 65-90, 65-A90, 70, B90, C90, C90A, E90, H90, C90GT
SA2631CE	03/13/03	4-PL Side Facing Divan	32-0149, 32-0133, 32-0194, 32-0248, 32-0227, 32-0355, 32-0362	Hawker Beechcraft	F90
SA2632CE	03/13/03	4-PL Side Facing Divan	32-0149, 32-0133, 32-0194, 32-0248, 32-0227, 32-0355, 32-0362	Hawker Beechcraft	99, 99A, A99A, B99, C99, <b>100</b> , A100, A100A, A100C, B100
SA2633CE	08/21/08	4-PL Side Facing Divan	32-0149, 32-0133, 32-0194, 32-0248, 32-0227, 32-0355, 32-0362	Hawker Beechcraft	200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, 300, 300LW, B300, B300C
SA2671CE	08/26/15	King Air Stretcher	32-0117, 32-0117-300, 32-0389, 32-0390	Hawker Beechcraft	200, B200, 200C, B200C, B200GT, B200CGT, 300, B300, B300C
SA2672CE	07/11/13	King Air Stretcher	32-0117	Hawker Beechcraft	99, 99A, A99, A99A, B99, C99, 100, A100, A100A, A100C, B100
SA2673CE	10/22/15	King Air Stretcher	32-0117	Hawker Beechcraft	65, A65, 65-80, 65-A80, A65-8200, 65-A80-8800, 65-B80, 65-88, 65-90, 65-A90, 70, B90, C90, C90A, E90, H90, C90GT, C90CTi
SA2674CE	07/11/13	Stretcher	32-0117	Hawker Beechcraft	F90
SA2715CE	11/22/03	Commuter Seats	42-0122, 42-0131	Cessna	401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C
SA2716CE	11/22/03	Commuter Seats	42-0121, 42-0132	Cessna	401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C
SA2774CE	09/03/10	Commuter Seats	18-0042, 18-0043, 32-0124, 32-0315, 32-0316, 32-0374, 18-0197, 17-0205, 17-0495, 32-0369, 32-0372, 32-0373, 17-0593	Hawker Beechcraft	200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200CGT, B200GT, B200T, 300, B300, B300C, 300LW
SA2775CE	12/12/03	Commuter Seats	18-0042, 18-0043, 32-0124, 32-0315, 32-0316, 32-0374, 18-0197, 17-0205, 17-0495, 32-0369, 32-0372, 32-0373, 17-0593	Hawker Beechcraft	100, A100, A100C, B100, 99, 99A, A99, A99A, B99, C99

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA2776CE	12/12/03	Commuter Seats	18-0042, 18-0043, 32-0124, 32-0315, 32-0316, 32-0374, 18-0197, 17-0205, 17-0495, 32-0369, 32-0372, 32-0373, 17-0593	Hawker Beechcraft	F90
SA2777CE	11/24/07	Commuter Seats	18-0042, 18-0043, 32-0124, 32-0315, 32-0316, 32-0374, 18-0197, 17-0205, 17-0495, 32-0369, 32-0372, 32-0373, 17-0593	Hawker Beechcraft	65, A65, 65-80, 65-A80, 65-B80, 65-88, 65-90, 65-A90, 70, B90, C90, C90A, E90, C90GT
SA2818SW	12/02/98	3-PL Side Facing Couch	42-0261, 42-0364, 42-0363	Cessna	441
SA2847CE	08/18/92	Stretcher	41-0111	Cessna	208, 208A, 208B
SA2878SW	01/02/02	2-PL Side Facing Couches	62-0258	Sabreliner	NA-265-60, NA-265-65, NA-265-70, NA-265-80
SA2885SW	12/05/01	2-3 PL Side Facing Seats	62-0262, 62-0263, 62-0292, 62-0293	Avion Marcel Dassault - BA	Falcon 10
SA2893SW	08/05/04	2-3 PL Side Facing Seats	62-0283, 62-0284, 62-0285, 62-0402, 62-0403	Gulfstream	G-159, G-1159, G-1159A, G-1159B, G-IV
SA2RM	12/28/90	AFT Baggage	42-0119	Cessna	421, 421A, 421B
SA3894NM	05/30/13	Stretcher	32-0221K-101, 32-0221K-102	Mitsubishi Heavy Industries	MU-300
SA3895NM	05/30/13	Stretcher	32-0221K-101, 32-0221K-102	Hawker Beechcraft	400, 400A, 400T
SA4054SW	04/22/02	1-2-3 PL Side Facing Seat (Frame Only)	42-0145, 42-0146, 42-0147, 42-0179, 42-0289, 42-0290, 42-0288, 42-0288-NF, 42-0354, 42-0354-NF	Cessna	500, 500S, 550, 560, 501, 551

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
SA4125SW	09/23/96	2-PL Side Facing Seat (Frame Only) & Side Facing only	62-0178	Israel Aircraft Industries	1121, 1121A, 1121B, 1123, 1124, 1124A
SA4147SW	05/23/02	1-2-3-4 PL Side Facing Seat	62-0166, 62-0167, 62-0168, 62-0172, 62-0188, 62-0232, 62-0233, 62-0234, 62-0235, 62-0236, 62-0286K, 62-0359, 62-0360, 62-0361, 62-0346, 62-0408	Hawker	DH. 125 Series, BH. 125 Series, HS. 125 Series, Bae. 125 Series, Hawker 800, Hawker 1000, Hawker 800XP
SA4157SW	03/31/04	1-2-3 PL Side Facing Seat (Frame Only)	32-0151, 32-0152, 32-0153, 32-0394, 32-0395	Hawker Beechcraft	65, <b>A65</b> , A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 65-88, 65-90, 65-A90-1, 65-A90-2, 65-A90-3, 65-A90-4, 65-A90, B90, C90, C90A, C90GT, E90, F90, 99,99A, A99, A99A, B99, C99, 100, A100, A100A, A100C, B100, 200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, B200GT, B200CGT, 300, B300, B300C, 300LW
SA4548SW	11/14/97	Side Facing Toilet Seat Frame	32-0177	Mitsubishi Hawker Beechcraft	MU-300, MU-300-10 400, 400A
SA47RM	04/19/01	Single Seat in AFT Baggage Compartment	90270-1	Cessna	500
SA51RM	02/06/04	Tailcone Ski Rack	42-0174K, 42-0175K, 42-0249K, 42-0250K	Cessna	500, 550
SA52RM	05/13/97	Stretcher	42-0197K-XX	Cessna	500, 550, 560, S550
SA54RM	10/18/96	Tailcone Storage Box & Engine Cover Storage Box	42-0190, 42-0191, 42-0192, 42-0193	Cessna	500
SA58RM	05/20/08	3-PL AFT Couch	90500-1, 90500-101, 90500-102, 90500-103, 90500-104, 90530-1, 90530-101, 90750-1, 90750-101, 90750-102, 90750-103, 90750-104, 90750-105	Cessna	500, 550
ST00283WI	02/08/95	Side Facing Divan	42-0169	Cessna	500, 550, 501, 551

# United States STC

Last Updated: 12/13/2017

<u>STC NUMBER</u>	<u>DATE ISSUED</u>	<u>NOMENCLATURE</u>	<u>AVFAB P/N</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODELS</u>
ST00716WI	11/02/98	Shoulder Harness Kit	42-0254K, 42-0259K, 42-0287K, 42-0304K, 42-0305K	Cessna	501, 551, 500, 550, S550, 560, 650
ST01042WI	01/02/02	Structural Repair Kit - tubular seat frames	42-0310K, 42-0311K, 42-0312K, 42-0313K	Cessna	550, 550
ST01043WI	01/02/02	Structural Repair Kit - tubular seat frames	42-0310K, 42-0311K, 42-0312K, 42-0313K	Cessna	501, 551
ST01139WI	07/17/06	1 or 2 PL Divan	42-0323, 42-0326, 42-0348	Cessna	560 (Serial # 539 through 5000)
ST01262WI	07/28/04	1-2-3 PL Side Facing Seat	42-0226, 42-0237, 42-0238	Cessna	650 (Serial # 650-0023 & On)
ST01475WI	03/12/08	AFT Cabin Divider	42-0341K	Cessna	550 (S/N 0002 through 0505)
ST01548WI	06/17/09	Seat Headrest Assemblies	42-0365K, 42-0366K	Cessna	560, 650, S550, 550
ST01572WI	12/14/09	2-PL Divan, AFT Toilet, Dividers, Lighting	32-0377	Hawker Beechcraft	400, 400A
ST01580WI	08/29/13	2-PL Side Facing Divan	62-0255K, 62-0273K	Learjet	55, 55B, 55C, 60
ST157RM	04/19/01	Dual AFT Lounge Seats	90281-1, 90281-101, 90281-102	Cessna	550